


# REFERENCE 72


Page 1

Photo No. 1




Photographer: Jack Brunner Date: 02/18/92 Time: 10:35 a.m. Direction: North  
Description: Eastern edge of landfill, monitoring well in foreground; note that no fence is present between the landfill and the railroad tracks

Photo No. 2



Photographer: Jack Brunner Date: 02/18/92 Time: 10:40 a.m. Direction: Northwest  
Description: Abandoned American Add Mixtures building in northeast corner of landfill

**Photo No. 3**



**Photographer: Jack Brunner Date: 02/18/92 Time: 10:45 a.m. Direction: South**  
**Description: Pond water south and west of the American Add Mixtures building; gas seen bubbling up in this water**

**Photo No. 4**




**Photographer: Jack Brunner Date: 02/18/92 Time: 10:50 a.m. Direction: west**  
**Description: Unfilled area of the facility's northwest corner; note exposed debris, standing water, and lack of a fence on the northern border**

**Photo No. 5**




**Photographer: Jack Brunner Date: 02/18/92 Time: 10:55 a.m. Direction: Downward**  
**Description: View of standing water in the northwestern corner of the landfill, note leachate on right of photograph and exposed debris**

**Photo No. 6**



**Photographer: Jack Brunner Date: 02/18/92 Time: 10:55 a.m. Direction: Downward**  
**Description: Standing water in the northwest corner of the landfill; PRC noted smoke or steam (center of photograph) in this area that may indicate an underground fire**

**Photo No. 7**



**Photographer: Jack Brunner   Date: 02/18/92   Time: 11:15 a.m.   Direction: East**  
**Description: Capped area of landfill; clay spreading equipment in background**